



**FUSIBLES**


FUNCION NOMINAL DE TEMPERATURA Tf[°C]				CORRIENTE NOMINAL (A)	METODO DE SOLDADURA
--	--	--	--	--------------------------	---------------------

T06F	65	T4F	127	1~2	standard
T0F	76	T13F	133		
T1F	86	T5F	136		
T2F	102	T6F	139		
T3F	115	T7F	145		

V06F	65	V4F	127	2~3	standard
V0F	76	V13F	133		
V1F	86	V5F	136		
V2F	102	V6F	139		
V3F	115	V7F	145		

L06F	65	L13F	133	3~5	standard
L2F	102	L5F	136		
L3F	115	L6F	139		
L4F	127	L7F	145		



HU06F	65	HU4F	127	2~3	standard
HU0F	76	HU13F	133		
HU1F	86	HU5F	136		
HU2F	102	HU6F	139		
HU3F	115	HU7F	145		

N06	65	N4F	127	1	standard
N0F	76	N13F	133		
N1F	86	N5F	136		
N2F	102	N6F	139		
N3F	115	N7F	145		
N0X	76				

N1X	86	N13X	133	1	para maquina de soldar
N2X	102	N5F	136		
N3X	115	N6F	139		
N4X	127	N7F	145		